ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura
Street ID	**Street Name**	**Significant Landmark**
W0720, W0851, W0989, W0991, W0981, W0857, W0853, W	NA, 1st Main Rd	Vinayaka Layout
Segment No.	**Total Length (m)**	
7/C-W0720/S032900	1040.66	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	191.55	77.602356	13.052568	77.604083	13.052208	1st Main Road	Coffee Board Layout
2	54.87	77.603499	13.051858	77.603429	13.051366	7th cross	Dead End
3	64.08	77.603429	13.052302	77.603322	13.051732	6th cross	Dead End
4	41.74	77.603161	13.051779	77.603091	13.051408	5th cross	Dead End
5	108.37	77.602968	13.052411	77.602807	13.051445	4th cross	Dead End
6	110.18	77.602673	13.052474	77.602506	13.051492	3rd Cross	Dead End
7	111.22	77.602351	13.052558	77.602190	13.051565	2nd Cross	Dead End
8	77.03	77.601997	13.052281	77.601900	13.051591	1st cross	Dead End
9	281.62	77.601348	13.051638	77.603917	13.051272	Vinayaka Layout Main Road	Coffee Board Layout

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Package-3, includes 4 works of Rs 249.00 Lks. 1) Improvements to CA ites providing chain link Fencing in Coffee board layout and Surroundings ares in	24900000	2017-18
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender	1.Desilting Of Drains.2.Construction of RCC Drains with Covering slab.3.Providing and Laying SDBC.	007-18-000017, 007-18-000018,007-18-000009,007-18-
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/72/18-19	26/07/2018	

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
18/09/2018	17/09/2020	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
B.B.Umesh		0.00
Phone No.	**E-Mail ID**	
9886213563		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Pushpalatha.N.D
Date of Inspection	**Remarks**	
18/09/2018		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0720, W0851, W0989, W0991,

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0720, W0851, W0989, W0991,

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0720, W0851, W0989, W0991,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	R.L.Parameshwaraiah	22/09/2018	18/10/2018	As proposed
SE	Vasu K M	19/09/2018	18/10/2018	Completed
EE	Mohandas H.T	19/09/2018	18/10/2018	verified
AEE	H.Ranganath	18/09/2018	18/10/2018	Verified
AE	Pushpalatha.N.D	18/09/2018	18/10/2018	Mobile Verification Done
AE	Pushpalatha.N.D	18/09/2018	18/10/2018	Forwarded

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0720, W0851, W0989, W0991,